
## ROADWORTHINESS (RW) AND TACHOGRAPH & LICENSING (T&L) ROADSIDE INSPECTIONS

Please note: When statistics from this report are used or published the source should be acknowledged.


-RSA






## **ROADWORTHINESS (RW) INSPECTIONS DEFECTS** Top 10 Defects detected Roadside (RW) 2022 Top 10 Defects detected Roadside (RW) 2023 Top 10 Defects detected Roadside (RW) 2024 Lamps, Reflectors & Electrical Equipment Lamps, Reflectors & Electrical Equipment Lamps, Reflectors & Electrical Equipment 4,043 4,047 3,259 Condition/Operation Condition/Operation Condition/Operation 1,497 1,904 1,774 1,126 1,075 921 Glazing, Mirrors & Wiper Systems Condition Cab and Bodywork Condition Glazing, Mirrors & Wiper Systems Condition 855 1,048 917 Cab and Bodywork Condition Cab and Bodywork Condition Glazing, Mirrors & Wiper Systems Condition 672 Braking Equipment Condition 678 Braking Equipment Condition Number Plates 661 674 627 624 Number Plates Number Plates Braking Equipment Condition 622 519 Lamps, Reflectors & Electrical Equipment Condition 430 Steering Equipment Condition Steering Equipment Condition 451 381 Chassis Condition Suspension System Condition Steering Equipment Condition Lamps, Reflectors & Electrical Equipment Condition 417 Suspension System Condition Suspension System Condition 278 Lamps, Reflectors & Electrical Equipment Condition 378 Chassis Condition Chassis Condition Top 10 Dangerous Defects detected Roadside (RW) 2022 Top 10 Dangerous Defects detected Roadside (RW) 2023 Top 10 Dangerous Defects detected Roadside(RW) 2024 Please note: When statistics from this report are used or published the source should be acknowledged.

## TACHOGRAPH AND LICENSING (T&L) INSPECTIONS INFRINGEMENTS Top 10 Infringements (T&L) detected - 2022 Top 10 Infringements (T&L) detected - 2023 Top 10 Infringements (T&L) detected - 2024 Fail to take adequate break - Driver 4,722 Fail to take adequate break - Driver 5,377 Fail to take adequate break - Driver 3,864 1,608 1,809 1,517 Fail to take daily rest period - Driver Fail to take daily rest period - Driver Fail to take daily rest period - Driver Insufficient obligatory break taken - 20 < ... <= 30 Insufficient obligatory break taken - 20 < ... <= 30 Insufficient obligatory break taken - 20 < ... <= 30 817 1,537 1.126 Insufficient obligatory break taken - ... <= 10 min -706 Exceed Daily Driving Time - Driver Fail to take weekly rest 807 Driver Insufficient obligatory break taken - 10 < ... <= 20 Fail to take weekly rest Driver to fail to use a record sheet 552 min - Driver 514 Insufficient obligatory break taken - 10 < ... <= 20 m.. 422 Exceed Daily Driving Time - Driver Driver card not used Insufficient obligatory break taken - ... <= 10 min -492 Fail to take weekly rest Driver card not used 408 Driver Insufficient obligatory break taken - 10 < ... <= 20 Driver card not used Driver to fail to use a record sheet min - Driver Fail to ensure correct functioning of the digital tac.. 347 Insufficient obligatory break taken - ... <= 10 min - D.. 401 439 Exceed Daily Driving Time - Driver Fail to ensure correct functioning of the digital $\label{eq:Fail} \textit{Fail to ensure correct functioning of the digital}$ 250 Driver to fail to use a record sheet tachograph - Operator tachograph - Operator p 10 Very Serious Infringements (VSI) & Most Serious Top 10 Very Serious Infringements (VSI) & Most Serious Please note: When statistics from this report are used or published the source should be acknowledged. Top 10 Very Serious Infringements (VSI) & Most Serious Top 10 Very Serious Infringements (VSI) & Most Serious





## **OUT OF STATE DEFECTS & INFRINGEMENTS** Top 10 Defects detected Roadside (RW) - 2022 Top 10 Defects detected Roadside (RW) - 2023 Top 10 Defects detected Roadside (RW) - 2024 Lamps, Reflectors & Electrical Lamps, Reflectors & Electrical Equipment Condition/Operation Lamps, Reflectors & Electrical 307 330 Equipment Condition/Operation Equipment Condition/Operation Tyre Condition 208 168 Tyre Condition 162 Braking Equipment Condition 97 Braking Equipment Condition 94 Cab and Bodywork Condition Glazing, Mirrors & Wiper Systems Condi.. Glazing, Mirrors & Wiper Systems Condi... Glazing, Mirrors & Wiper Systems Braking Equipment Condition Number Plates Number Plates 62 Number Plates Cab and Bodywork Condition Cab and Bodywork Condition Chassis Condition Steering Equipment Condition Suspension System Condition 51 Chassis Condition Chassis Condition Suspension System Condition Anti-lock Braking System (ABS) Suspension System Condition Steering Equipment Condition Wheel Condition Lamps, Reflectors & Electrical Equi.. 16 Steering Equipment Condition Top 10 Infringements (T&L) detected - 2022 Top 10 Infringements (T&L) detected - 2023 Top 10 Infringements (T&L) detected - 2024 ${\it Please note: When statistics from this report are used or published the source should be acknowledged.}$